ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0363	R H B Colony 1st Main Rd	Shettyhalli Railwaygate
Segment No.	**Total Length (m)**	
12/S-W0363/S011216	265.13	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	265.13	77.519064	13.073658	77.518288	13.071385	W0363	W0363

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Restoration of Road cut portion done by BWSSB of water line and sanitary line in Shettyhalli old village area in ward no.12 Shettyhalli Sub Division	9980000	2019
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender		012-19-000066
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/389/19-20	23/08/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/01/2020	13/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Professional Global Infrastructure Pvt Ltd		2074941.00
Phone No.	**E-Mail ID**	
9900510303		

Scanned by CamScanner

Name

old village Shettyhalli

Field Inspection Details

Number of Trees

2

Date of Inspection

16/01/2020

Any Other Information

Shetty halli roads

Remarks

restorationwork

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

DASARAHALLI

Scanned by CamScanner